

*** MATERIAL SAFETY DATA SHEET ***
SOLVENT RESISTANT LUBE (PART # U000-002)
(PAGE 1)
DATE OF PREP: 01/27/04

1. PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NAME:	SOLVENT RESISTANT LUBE
CHEMICAL NAME:	Mixture
DOT SHIPPING NAME:	N/A
SARA TITLE III SECTION 313:	N/A

MANUFACTURER CON-TROL-CURE 1229 W. Cortland St. Chicago, IL 60614	EMERGENCY TELEPHONE NUMBER INFOTRAC: 1-800-535-5053 HMIS RATING: 1-1-0
---	--

2. COMPOSITION

None Hazardous

3. EMERGENCY AND FIRST AID PROCEDURES

Eye Contact:	Flush with water for 15 minutes. If irritation persists, seek medical attention.
Skin Contact:	Wash with soap and water. If irritation occurs, seek medical attention.
Inhalation:	Remove to fresh air. If breathing difficulties arise, seek medical attention.
Ingestion:	DO NOT INDUCE VOMITING! Get medical attention immediately.

4. PHYSICAL AND CHEMICAL PROPERTIES

Boiling Point (deg F):	N/D	Specific Gravity: (water = 1)	1.0
Solubility in Water:	Soluble	Evaporation Rate: (ether = 1)	N/D
Percent Volatile:	NEGLIGIBLE	Vapor Density:	>5
Appearance:	Purple	Odor:	Mild

5. EFFECTS OF OVEREXPOSURE

Eyes: May cause eye irritation.

Skin: Prolonged or repeated contact may result in irritation.

Inhalation: Heating can generate vapors that may cause respiratory irritation.

Ingestion: Can cause stomach ache and vomiting.

*** MATERIAL SAFETY DATA SHEET ***
SOLVENT RESISTANT LUBE (PART # U000-002)
(PAGE 2)
DATE OF PREP: 01/27/04

6. SPECIAL PROTECTION INFORMATION

Respiration Protection: Normally not needed for typical use situations.

Ventilation: Normal local exhaust should be sufficient.

Skin Protection: Chemical resistant gloves/aprons to avoid contact.

Eye Protection: Safety goggles or face shield.

7. STABILITY AND REACTIVITY

Stability: STABLE Hazardous Polymerization: WILL NOT OCCUR

Incompatibility: STRONG OXIDANTS AND ACIDS

Hazardous Decomposition Products: OXIDES OF CARBON

8. SPILL/LEAK/STORAGE PROCEDURES

Precautions in Case of Spill or Release: Recover free product. Add sand, earth or other absorbant to spill area or flush sparingly with water. Minimize skin contact. Keep out of sewers and watercourses.

Waste Disposal Method: Assure compliance with all federal, state and local regulations.

Handling and Storage Precautions: Keep containers away from heat, sparks and open flame. Keep containers closed when not in use. Do not store or mix with strong oxidizers.

9. FIRE FIGHTING MEASURES

Flash Point Range: Over 400 deg F

Extinguishing Media: Foam, Dry Chemical, Carbon Dioxide

Unusual Fire/Explosion: Hazards: Pressure will increase in overheated closed containers.

Fire Fighting Procedures: Use supplied-air respirator in confined spaces.

The above information is accurate to the best of our knowledge, however it is not warranted to be. Users are advised to confirm that the information is current, applicable and suitable to their circumstances.