

PRESS RELEASE

FOR IMMEDIATE RELEASE

Contact: Corey Gunzberg
Marketing Manager
coreyg@uvps.com
773-248-0099

“HOW TO SELECT A RADIOMETER” MANUAL COMPLIMENTS NEW RADIOMETER MODELS

CHICAGO, April 28, 2005 – Choosing the right radiometer can be a challenging proposition for many UV users. There are dozens of options and it is not always clear which style and features best suit a specific UV environment. To help users sort through the varied choices of UV measurement devices, UV Process Supply (Chicago, IL) has developed a guide to simplify the selection process.

The “How To Select a Radiometer” manual describes the different styles of UV monitoring choices and specifies which types benefit each application. A handy table clearly displays radiometer specifications and applications. As well, a suggested “Good, Better, Best” chart directs users to the recommended units best suited for their unique curing challenges. There is an in depth discussion that covers the types of radiometers available, why a radiometer is actually needed, and how to make best use of a radiometer.

The release of this “How To” manual marks the introduction of the new line of CON-TROL-CURE® radiometers available exclusively through UV Process Supply. Over the coming months, CON-TROL-CURE will be rolling out its new line of radiometers, adding to its already comprehensive selection. These new radiometers, with over 20 models, will be competitively priced and unique in their function. For example, the first released models include the thinnest available “pass through” radiometer and a profiling radiometer that captures dose, intensity and temperature and displays this data via an on-board graphical screen—eliminating the need to connect to a computer to view detailed graphs and results.

Since 1979, UV Process Supply has provided goods and services for the UV curing market. These products reinforce UV Process Supply’s position as *the complete source for all your UV curing needs.*

The “How To Select a Radiometer” manual is available free of charge through UV Process’ website at www.uvprocess.com/manuals. For specifications on their full line of UV Radiometers, contact UV Process Supply at their toll-free number 800-621-1296 or 773-248-0099. UV Process Supply is also accessible via fax at 800-99FAXUV or 773-880-6647, via email at info@uvps.com, or via their website at www.uvprocess.com.

###